

FAAST XT & XT Pro Release Notes

Filename: S04-0182-010

Sensor bootloader version: 1.3, 1.4

Sensor application version: 1.12

Comms bootloader version: 1.5, 1.6

Comms application version: 1.22

Models affected: All

Description of Changes:

- Added additional recovery mechanism for display and keypad in the event they become unresponsive.

Filename: S04-0182-009

Sensor bootloader version: 1.3, 1.4

Sensor application version: 1.11

Comms bootloader version: 1.5, 1.6

Comms application version: 1.21

Models affected: All

Description of Changes:

- Fixed issue where display and keypad could become unresponsive

FAAST XT Release Notes

Filename: S04-0182-008

Sensor bootloader version: 1.3, 1.4

Sensor application version: 1.11

Comms bootloader version: 1.5, 1.6

Comms application version: 1.20

Models affected: All

Description of Changes:

- Fixed time fault errors that may occur during normal operation. Corrected menus for foreign language to show inlet smoke id.

FAAST XT Release Notes

Filename: S04-0182-004

Sensor bootloader version: 1.3

Sensor application version: 1.7

Comms bootloader version: 1.5

Comms application version: 1.15

Models affected: All

Description of Changes:

- User Interface
 - The chamber obscuration was moved from the Home Screen to the **Diagnostics** menu.
 - The **Functions** menu has been re-ordered to provide faster access to the **Reset** function.
- Webservice
 - Added Device information page.
- Modbus
 - Configuration changes are now possible when a device is in CONFIGURATION or DISABLE mode.
 - CLIP devices now support smoke referencing via Modbus.
- General changes
 - Firmware upgrade events are now logged.
 - The default configuration time stamp is 1-Jan-2015.

